

Table of Contents

Dedication	iii
Preface	xvii

Chapter 1: Introduction to NX

Introduction to NX	1-2
System Requirements	1-4
Getting Started with NX	1-4
Important Terms and Definitions	1-6
Understanding the Functions of the Mouse Buttons	1-10
Quick Access Toolbar	1-12
Ribbon	1-14
Status Bar	1-19
Hot Keys	1-19
Dialog Boxes in NX	1-19
Selecting Objects	1-20
Deselecting Objects	1-21
Self-Evaluation Test	1-21

Chapter 2: Creating Sketches, Dimensions, Base Features and Drawings

Introduction	2-2
Starting NX	2-2
Starting a New Document in NX	2-3
Invoking Different NX Environments	2-8
Creating Three Fixed Datum Planes (XC-YC, YC-ZC, XC-ZC)	2-8
Displaying the WCS (Work Coordinate System)	2-9
Creating Sketches	2-10
Creating Sketches in the Sketching Environment	2-10
Creating Sketches in the Modeling Environment	2-14
Sketching Tools	2-15
Drawing Sketches Using the Line Tool	2-15
Using Help Lines to Locate Points	2-18
Drawing Individual Lines	2-19
Drawing Arcs	2-19
Drawing Circles	2-21
Drawing Rectangles	2-22
Placing Points	2-23
Drawing Ellipses or Elliptical Arcs	2-29
Drawing Conics	2-31

Drawing Studio Splines	2-31
Filleting Sketched Entities	2-32
The Drawing Display Tools	2-34
Fitting Entities in the Current Display	2-35
Zooming an Area	2-36
Dynamic Zooming	2-36
Panning Drawings	2-36
Fitting View to Selection	2-37
Restoring the Original Orientation of the Sketching Plane	2-37
Setting Selection Filters in the Sketch in the Sketch Environment	2-37
Selecting Objects	2-37
Deselecting Objects	2-38
Using Snap Point Options While Sketching	2-39
Deleting Sketched Entities	2-40
Dimensioning Sketches	2-40
Limiting editable curves to a region of a sketch	2-45
Exiting the Sketch Environment	2-46
Creating Base Features by Extruding	2-46
Invoking the drafting environment in the current part file	2-47
Tutorial 1	2-48
Tutorial 2	2-54
Tutorial 3	2-61
Self-Evaluation Test	2-67
Review Questions	2-68
Exercise 1	2-69
Exercise 2	2-69

Chapter 3: Adding Geometric and Dimensional Constraints to Sketches

Constraining Sketches	3-2
Concept of Constrained Sketches	3-2
Under-Constrain	3-2
Fully-Constrain	3-2
Over-Constrain	3-2
Dimensioning Sketches	3-3
Applying Dimensions by Using the Rapid Dimension Tool	3-4
Applying Linear Dimensions	3-4
Applying Radial Dimensions	3-7
Applying Angular Dimensions	3-8
Applying Perimeter Dimensions	3-8
Geometric Constraints	3-9
Applying Additional Constraints Individually	3-9
Applying Symmetry Constraint	3-12
Converting a Sketch Entity or Dimension into a Reference Entity or Reference Dimension	3-13
Creating Alignment Constraints	3-13

Tutorial 1	3-15
Tutorial 2	3-20
Tutorial 3	3-24
Self-Evaluation Test	3-27
Review Questions	3-28
Exercise 1	3-29
Exercise 2	3-30

Chapter 4: Editing, Extruding, and Revolving Sketches

Editing Sketches	4-2
Trimming Sketched Entities	4-2
Extending Sketched Entities	4-3
Creating a Corner between Sketched Entities	4-4
Moving Sketched Entities by Using the Move Curve Tool	4-5
Offsetting Sketched Entities by Using Offset Move Curve	4-11
Modifying Entities by Using the Resize Curve Tool	4-13
Modifying Chamfer in Sketched Entities by Using Resize Chamfer Curve Tool	4-15
Deleting Sketched Entities by Using Delete Curve Tool	4-16
Offsetting Sketched Entities	4-17
Mirroring Sketched Entities	4-19
Creating a Linear Sketch Pattern	4-20
Creating a Circular Sketch Pattern	4-21
Creating a General Sketch Pattern	4-23
Trim Associative Curve	4-16
Scale Curve	4-12
Editing Sketched Entities by Dragging	4-23
Exiting the Sketch Environment	4-24
Changing the View of the Sketch	4-25
Creating Base Features by Extruding	4-25
Extrude Dialog Box Options	4-26
Creating Solid Revolved Bodies	4-33
Transforming 3D Objects	4-38
Copying, Moving, and Rotating Objects	4-40
Hiding Entities	4-47
Showing Hidden Entities	4-48
Hiding All Entities Using a Single Tool	4-48
Rotating the View of a Model in 3D Space	4-48
Setting Display Modes	4-49
Tutorial 1	4-50
Tutorial 2	4-52
Tutorial 3	4-57
Self-Evaluation Test	4-59
Review Questions	4-60
Exercise 1	4-61
Exercise 2	4-61

Chapter 5: Working with Datum Planes, Coordinate Systems, and Datum Axes

Additional Sketching and Reference Planes	5-2
Types of Datum Planes	5-3
Creating Datum Coordinate Systems	5-10
Creating Fixed and Relative Datum Axes	5-14
Other Extrusion Options	5-18
Specifying the Boolean Operation	5-18
Other Extrusion Termination Options	5-21
Projecting External Elements	5-22
Tutorial 1	5-24
Tutorial 2	5-29
Tutorial 3	5-34
Self-Evaluation Test	5-38
Review Questions	5-39
Exercise 1	5-40
Exercise 2	5-41
Exercise 3	5-43

Chapter 6: Advanced Modeling Tools-I

Advanced Modeling Tools	6-2
Creating Holes by Using the Hole Tool	6-2
Creating Custom Holes	6-2
Creating Threaded Hole	6-4
Creating Hole Series	6-5
Creating Grooves	6-6
Creating Rectangular Grooves	6-6
Creating Ball End Grooves	6-8
Creating U Grooves	6-9
Creating Slots	6-10
Creating Rectangular Slots	6-11
Creating Ball-End Slots	6-13
Creating U-Slots	6-14
Creating T-Slots	6-16
Creating Dove-Tail Slots	6-17
Creating Ribs	6-19
Creating Chamfers	6-22
Creating a Chamfer Feature Using the Symmetric Method	6-22
Creating a Chamfer Feature Using the Asymmetric Method	6-24
Creating a Chamfer Feature Using the Offset and Angle Method	6-25
Creating an Edge Blend	6-25
Introduction to Algorithmic Modeling	6-31
Tutorial 1	6-33
Tutorial 2	6-40
Tutorial 3	6-47
Self-Evaluation Test	6-52

Review Questions	6-52
Exercise 1	6-53
Exercise 2	6-54
Exercise 3	6-56

Chapter 7: Advanced Modeling Tools-II

Advanced Modeling Tools	7-2
Pattern Feature Tool	7-2
Creating a Linear Pattern	7-2
Creating a Circular Pattern	7-8
Creating a Polygon Pattern	7-11
Creating a Spiral Pattern	7-12
Creating a Pattern Along a Curve	7-14
Creating a General Pattern	7-15
Creating a Reference Pattern	7-16
Creating Patterns by Defining Boundary	7-16
Creating a Fill Pattern	7-17
Mirror Feature Tool	7-20
Mirror Face Tool	7-21
Mirror Geometry Tool	7-21
Sweeping Sketches Along the Guide Curves	7-22
Creating Swept Features	7-24
Creating Tubes or Cables	7-27
Creating Threads	7-28
Creating Symbolic Threads	7-29
Creating Detailed Threads	7-31
Creating Shell Features	7-33
Editing Features	7-34
Editing a Hole Feature	7-34
Editing the Positioning of a Groove Feature	7-35
Editing the Parameters of Features	7-35
Editing the Parameters of Features with Rollback	7-35
Editing Sketches of the Sketch-based Features	7-36
Reordering Features	7-36
Creating Drafts	7-36
Creating Lattice	7-39
Measuring Objects	7-42
Tutorial 1	7-45
Tutorial 2	7-49
Tutorial 3	7-52
Tutorial 4	7-57
Tutorial 5	7-63
Self-Evaluation Test	7-67
Review Questions	7-68
Exercise 1	7-69
Exercise 2	7-70
Exercise 3	7-71

Chapter 8: Assembly Modeling-I

The Assembly Environment	8-2
Invoking the Assembly Environment	8-2
Invoking the Assembly Environment Using the New Dialog Box	8-2
Invoking the Assembly Environment in the Current Part File	8-2
Types of Assembly Design Approaches	8-3
Creating Bottom-up Assemblies	8-3
Placing Components in the Assembly Environment	8-4
Changing the Reference Set of a Component	8-6
Applying Assembly Constraints to Components	8-7
Applying Joints to Components in Assembly	8-15
Points to Remember while Assembling Components	8-16
Creating a Pattern Component in an Assembly	8-17
Replacing a Component in an Assembly	8-18
Moving a Component in an Assembly	8-20
Mirroring a Component in an Assembly	8-24
Modifying a Component in the Assembly File	8-27
Tutorial 1	8-41
Tutorial 2	8-42
Self-Evaluation Test	8-55
Review Questions	8-56
Exercise 1	8-57
Exercise 2	8-63
Exercise 3	8-67
Exercise 4	8-70

Chapter 9: Assembly Modeling-II

The Top-down Assembly Design Approach	9-2
Creating Components Using the Top-down Assembly Design Approach	9-2
Creating Subassemblies	9-4
Editing Assembly Constraints	9-5
Checking the Interference between the Components of an Assembly	9-5
Checking Interference Using the Simple Interference Tool	9-5
Checking Interference Between the Assembly Components	9-7
Checking Interference and Clearance, and Analyzing Cross-sections of Components Using the View Section Tool	9-12
Creating Exploded Views of an Assembly	9-16
Digital Mock Up Application (DMU)	9-20
Tutorial 1	9-22
Tutorial 2	9-26
Tutorial 3	9-31
Tutorial 4	9-39
Self-Evaluation Test	9-46
Review Questions	9-46
Exercise 1	9-47
Exercise 2	9-53
Exercise 3	9-59

Chapter 10: Surface Modeling

Introduction to Surface Modeling	10-2
Invoking the Shape Studio Environment	10-2
Creating an Extruded Surface	10-2
Creating a Revolved Surface	10-3
Creating a Combined Surface	10-4
Creating a Surface Using the Through Curves Tool	10-6
Creating a Surface Using the Through Curve Mesh Tool	10-8
Creating a Surface Using the Four Point Surface Tool	10-9
Creating Planar Surfaces from 2D Sketches and Edges of Solid or Surface	10-10
Editing Surface Using the X-Form Tool	10-11
Creating an N-Sided Surface	10-12
Creating a Silhouette Flange Surface	10-15
Extending a Surface Using the Law Extension Tool	10-20
Creating a Surface Offset Using the Offset Surface Tool	10-24
Trimming and Extending a Surface Using the Trim and Extend Tool	10-24
Trimming a Sheet by Using the Trimmed Sheet Tool	10-26
Creating a Surface Using the Studio Surface Tool	10-29
Creating a Surface between Two Walls Using the Styled Blend Tool	10-31
Creating Surfaces Using the Styled Sweep Tool	10-36
Sewing Individual Surfaces into a Single Surface	10-37
Adding Thickness to a Surface	10-38
Adding a Draft	10-39
Tutorial 1	10-40
Tutorial 2	10-45
Self-Evaluation Test	10-53
Review Questions	10-54
Exercise 1	10-55
Exercise 2	10-56

Chapter 11: Advanced Surface Modeling

Creating Curves from Bodies	11-2
Creating Intersection Curves	11-2
Creating Section Curves	11-3
Creating Isoparametric Curves	11-8
Projecting Curves	11-10
Advanced Surface Modeling Tools	11-14
Creating Emboss Body on a Sheet or Solid Body	11-14
Creating Face Blend Features	11-15
Creating Bridge Surface Features	11-22
Tutorial 1	11-23
Tutorial 2	11-36
Tutorial 3	11-44
Self-Evaluation Test	11-56
Review Questions	11-56
Exercise 1	11-57
Exercise 2	11-58

Chapter 12: Generating, Editing, and Dimensioning the Drawing Views

The Drafting Environment	12-2
Invoking the Drafting Environment	12-2
Invoking the Drafting Environment Using the Drawing Template from the New Dialog Box	12-2
Invoking the Drafting Environment in the Current Part File	12-3
Editing the Drawing Sheet Parameters in the Drafting Environment	12-6
Types of Drawing Views in NX	12-6
Base View	12-6
Projected View	12-6
Detail View	12-7
Section View	12-7
Auxiliary View	12-7
Half-Section View	12-7
Revolved Section View	12-7
Break-Out Section View	12-7
Broken View	12-7
Generating Drawing Views	12-7
Generating Views Using the View Creation Wizard Tool	12-8
Generating the Base View	12-12
Generating the Orthographic Drawing Views Using the Projected View Tool	12-14
Generating the Detail View Using the Detail View Tool	12-16
Creating a Section Line	12-19
Generating Section Views Using the Section View Tool	12-20
Generating the Break-Out Section View	12-25
Generating the Broken View	12-27
Manipulating the Drawing Views	12-29
Moving the Drawing Views Using the Move/Copy View Tool	12-29
Aligning the Drawing Views Using the Align View Tool	12-30
View Boundary	12-33
Section in View Tool	12-33
Inserting a Drawing Sheet Using the New Sheet Tool	12-35
Modifying the Properties of the Generated Drawing View	12-35
Modifying the Scale Value of the Drawing View	12-36
Adding Dimensions to the Drawing Views	12-37
Generating Exploded Views of an Assembly	12-42
Creating Parts List and Associative Balloons	12-42
Creating a Parts List for an Assembly	12-42
Creating Associative Balloons	12-43
Creating a Tabular Note (Title Block)	12-44
Adding Multiline Text to a Drawing Sheet	12-46
Printing Tools	12-46
Print	12-47
Plot	12-47

Tutorial 1	12-48
Tutorial 2	12-54
Tutorial 3	12-58
Self-Evaluation Test	12-63
Review Questions	12-64
Exercise 1	12-65
Exercise 2	12-65

Chapter 13: Synchronous Modeling

Introduction	13-2
Synchronous Modeling Tools	13-2
Move	13-2
Move Edge	13-5
Pull Face	13-7
Offset Region	13-8
Offset Edge	13-10
Replace Face	13-11
Resize Blend	13-12
Reorder Blends	13-13
Resize Chamfer	13-14
Label Chamfer	13-14
Label Notch Blend	13-15
Radiate Face	13-15
Delete Face	13-16
Copy Face	13-19
Cut Face	13-21
Paste Face	13-21
Mirror Face	13-22
Pattern Face	13-22
Make Coplanar	13-24
Make Coaxial	13-26
Make Tangent	13-28
Make Symmetric	13-29
Make Parallel	13-30
Make Perpendicular	13-32
Make Offset	13-33
Linear Dimension	13-34
Angular Dimension	13-36
Radial Dimension	13-37
Group Face	13-39
Edit Cross Section	13-39
Tutorial 1	13-40
Tutorial 2	13-47
Self-Evaluation Test	13-54
Review Questions	13-55
Exercise 1	13-56
Exercise 2	13-56

CHAPTERS AVAILABLE FOR FREE DOWNLOAD

In this textbook, two chapters have been given for free download. You can download these chapters from our website www.cadcim.com. To download these chapters, use the following path: *Textbooks > CAD/CAM > Siemens > Siemens NX > Siemens NX 2026 with Videos for Designers, 17th Edition > Chapters for Free Download* and then click on the chapter name that you want to download.

Chapter 14: Sheet Metal Design

The Sheet Metal Module	14-2
Setting the Sheet Metal Part Properties	14-4
Creating the Base Feature	14-8
Adding Flanges to a Sheet Metal Part	14-10
Creating Contour Flanges	14-16
Creating Lofted Flanges	14-18
Adding a Jog to the Sheet	14-19
Bending the Sheet Metal Part	14-20
Unbending the Sheet Metal Part	14-21
Rebending the Sheet Metal Part	14-21
Filleting or Chamfering Corners	14-22
Closing the Corners of a Sheet Metal Part	14-22
Creating Dimples in a Sheet Metal Part	14-26
Creating Louvers in a Sheet Metal Part	14-28
Creating Drawn Cutouts in a Sheet Metal Part	14-30
Creating Beads in a Sheet Metal Part	14-31
Adding Gussets to a Sheet Metal part	14-34
Adding Hems	14-37
Creating a Sheet Metal Part Using Solid Body	14-40
Converting a Solid Part into a Sheet Metal Part	14-40
Ripping the Corners of a Solid Part	14-41
Creating the Flat Pattern of a Sheet Metal Part	14-42
Creating the Flat Pattern	14-42
Creating the Flat Solid	14-43
Exporting a Flat Pattern	14-44
Renewing Features	14-44
Tutorial 1	14-46
Tutorial 2	14-56
Self-Evaluation Test	14-62
Review Questions	14-63
Exercise 1	14-64
Exercise 2	14-65

Chapter 15: Concepts of Geometric Dimensioning and Tolerancing

History of Tolerances and Allowances	15-2
Methods of Tolerancing	15-2
Limit Dimensioning	15-3
Plus and Minus Tolerancing	15-4
Geometric Tolerances	15-4
Form Tolerances	15-10
Profile Tolerances	15-19
Orientation Tolerances	15-22
Location Tolerances	15-25
Runout Tolerances	15-29
Fits	15-33
Hole Basis System	15-33
Shaft Basis System	15-34
Standards of Fits	15-39
Standard Inch Fits	15-39
Standard Metric Fits	15-42
Tutorial 1	15-46
Self-Evaluation Test	15-52
Review Questions	15-53
Exercise 1	15-53
Index	I-1

This page is intentionally left blank.